


Ironing Board



Foam core board

Dowels or tube (shewers)

Fabric

White paint for legs

Iron

Cut from foam board one piece using pattern. Cover with fabric.

Cut 4 legs from dowels $3\frac{3}{4}$ " long.

Cut one end of each leg at apx 45° angle.

Paint legs.

With sharp object carefully make a small hole in fabric covered foam core board at each x. This should be done from the underside and only through under fabric and to foam center

Glue legs at holes. Angle each one and glue at angles to crisscross. Back legs will be inside front legs.

